



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, ILLINOIS 60604**

SUBJECT: CLEAN AIR ACT INSPECTION REPORT
BP at 1841 W. Devon, Chicago, Illinois

FROM: Virginia Galinsky, Environmental Engineer
AECAB (MN/OH)

THRU: Brian Dickens, Section Supervisor
AECAB (MN/OH)

TO: File

BASIC INFORMATION

Facility Name: BP

Facility Location: 1841 W. Devon Ave, Chicago, Illinois 60660

Date of Inspection: September 13, 2022

EPA Inspector(s):

1. Virginia Galinsky, Environmental Engineer
2. Constantinos Loukeris, Environmental Engineer

Other Attendees:

1. Syedazhar Hussain, Facility Manager

Contact Email Address: Lawrence.shell@yahoo.com

Purpose of Inspection: Gas station inspection under MACT Subpart CCCCCC

Facility Type: Gas station

Regulations Central to Inspection: 40 C.F.R. Part 63, Subpart CCCCCC, including but not limited to requirements for sources with more than 100,000 gallons per month of gasoline throughput to operate a vapor balance system which reduces emissions by at least 90%.

Arrival Time: 9:50 AM

Departure Time: 10:50 AM

Inspection Type:

- ☒ Unannounced Inspection
- ☐ Announced Inspection

OPENING CONFERENCE

- ☒ Presented Credentials
- ☒ Stated authority and purpose of inspection
- ☒ Provided Small Business Resource Information Sheet
- ☐ Small Business Resource Information Sheet not provided.
- ☐ Provided CBI warning to facility

The following information was obtained verbally from Syedazhar Hussain unless otherwise noted.

Staff Interview: We asked about records of testing done on the vent system and Mr. Hussain stated that he did not believe they were on-site but at a different location. We told him that we would email him which records we were requesting. He informed us that the gas station is a franchise location.

TOUR INFORMATION

EPA Tour of the Facility: Yes

Data Collected and Observations:

We used the GFX-320 FLIR Camera #2 to observe the entire gas station, including 3 vent pipes, a car being filled with gasoline, and the covers on the underground storage tanks. We did not observe any emissions from any of the sources observed.

Photos and/or Videos: were not taken during the inspection.

Field Measurements: were not taken during this inspection.

CLOSING CONFERENCE

- ☒ Provided U.S. EPA point of contact to the facility

Requested documents:

- A copy of the test report from the last air emission test conducted on the vapor balance system
- A copy of the Notification of Compliance Status required by 40 C.F.R. 63.11124

DIGITAL SIGNATURES

Report Author: _____

Section Supervisor: _____